

X-RITE SOLUTIONS

D50 Light Indicator

APPLICATION

Indicator label to check the lighting conditions of a proof or printed piece.

FEATURES AND SPECIFICATIONS

- 01** For proofs and printed materials.
- 02** Helps confirm D50 evaluation conditions.

Zanatto portfolio data.

<https://www.zanatto.com.br/categoria-produto/xrite/>

ZANATTO CONTACTS

Curitiba +55 (41) 3362-1415 | São Paulo +55 (11) 3775-2727

Porto Alegre +55 (51) 3337-7637 | falecom@zanatto.com.br

www.zanatto.com.br